




RasPiO® Breakout GPIO Breakout Board



Decide whether to assemble as Rev 1 or Rev 2. Solder the main 26-way female header underneath first, then the inner (female) and outer (male) headers on top, according to your preference. Ensure the board is attached to the Raspberry Pi® as shown above. (Raspberry Pi® not included)

RasPiO® Breakout Assembly Details, information and examples –

<http://RasP.iO/breakout>



Made in China - RasPiOBreakout-01